

# PicoMite Stepper Motor Control Reference

## 1. Overview

The STEPPER command provides a comprehensive system for controlling up to 4 stepper motor axes (X, Y, Z, and a rotary A axis) with support for G-code execution, acceleration planning, and hardware limit switches. It uses a dedicated 100kHz interrupt timer for smooth pulse generation.

## 2. Initialization & Configuration

### 2.1 Initialization

```
STEPPER INIT [arc_tolerance] [,buffer_size] [,estop_pin] [,estop_keep_enabled]
```

Initializes the stepper subsystem. Must be called before any other STEPPER commands.

- arc\_tolerance: (Optional) Tolerance for arc segmentation in mm (default: 0.05).
- buffer\_size: (Optional) Size of the G-code lookahead buffer (default: 32, max: 1024).
- estop\_pin: (Optional) Hardware emergency-stop input pin (active low).
- estop\_keep\_enabled: (Optional) 0 (default) = disable drivers on E-STOP, 1 = keep drivers enabled on E-STOP.

### 2.2 Axis Configuration

```
STEPPER AXIS axis, step_pin, dir_pin [, enable_pin] [, dir_invert] [, steps_per_unit] [, max_vel] [, max_accel] [, home_backoff_mm]
```

Configures a specific axis (X, Y, Z, or A).

- axis: X, Y, Z, or A. A is a rotary slave axis (units are degrees).
- step\_pin/dir\_pin: GPIO pins for Step and Direction signals.
- enable\_pin: (Optional) GPIO pin for Enable signal (active low).
- dir\_invert: (Optional) 1 to invert direction, 0 otherwise.
- steps\_per\_unit: (Optional) Steps required to move 1mm (X/Y/Z) or 1 degree (A).
- max\_vel: (Optional) Maximum velocity in mm/min (X/Y/Z) or deg/min (A).
- max\_accel: (Optional) Maximum acceleration in mm/s<sup>2</sup> (X/Y/Z) or deg/s<sup>2</sup> (A).
- home\_backoff\_mm: (Optional) Homing switch clear/backoff distance in mm (X/Y/Z only; ignored for A).

### 2.3 Limits & Safety

```
STEPPER HWLIMITS x_min, y_min, z_min [,x_max] [,y_max] [,z_max]
```

Configures hardware limit switch pins (active low). Pins must be mutually exclusive with AXIS/SPINDLE/E-STOP, except min and max may share the same pin on the same axis.

```
STEPPER LIMITS axis, min_mm, max_mm
```

Sets soft limits for an axis (X, Y, or Z) in mm. The A axis has no soft limits.

```
STEPPER ESTOP
```

Software emergency stop: halts motion immediately, clears buffer, and turns spindle off. Drivers are disabled unless estop\_keep\_enabled was set to 1 in STEPPER INIT.

If an INIT estop\_pin is configured, hardware E-STOP is monitored in ISR and terminates processing

# PicoMite Stepper Motor Control Reference

immediately under all circumstances (including homing).

## 3. Motion Control

### 3.1 G-Code Execution

```
STEPPER GC <gcode> [words...]
```

Executes a standard G-code command string.

Supported codes: G0, G1, G2, G3, G4, G28, G90, G91, G92, M3, M5.

Supported words: X, Y, Z, A, F, I, J, K, R, P.

M3/M5 and G4 are buffered and executed in-order with motion blocks.

G28 homes specified X/Y/Z axes (A axis is not homed). The A word is ignored on G2/G3 arcs.

Feedrate semantics: combined XYZ+A moves use mm/min over the XYZ Euclidean distance with A as a slave axis. A-only moves (no XYZ change) treat F as deg/min over |dA|.

Example: STEPPER GC G1 X10 Y5 F500

Example: STEPPER GC G1 A90 F360

```
STEPPER GS string$
```

Executes a G-code command supplied as a string expression. Accepts any MMBasic string variable, literal, or expression and passes it to the same G-code parser as STEPPER GC.

This is useful when G-code lines are constructed dynamically at runtime.

Supported codes: G0, G1, G2, G3, G4, G28, G90, G91, G92, M3, M5.

Supported words: X, Y, Z, A, F, I, J, K, R, P.

Example: STEPPER GS "G1 X" + STR\$(x\_pos) + " Y" + STR\$(y\_pos) + " F500"

Example: STEPPER GS gcode\$

```
STEPPER GCODE G0|G1|G2|G3|G4|G28|G90|G91|G92|M3|M5 [, X, x] [, Y, y] [, Z, z] [, A, a] [, F, feed] [, I, i] [, J, j] [, K, k] [, R, r] [, P, ms]
```

Alternative syntax for adding motion commands to the buffer. All parameters must be comma separated. The A axis is rotary; A units are degrees and the A word is ignored on G2/G3 arcs.

G4 uses P in milliseconds (for example: STEPPER GCODE G4, P, 500).

Example: STEPPER GCODE G1, X, 10, Y, 5, F, 500

Example: STEPPER GCODE G1, A, 90, F, 360

### 3.2 Manual Positioning

```
STEPPER POSITION HOME
```

Sets all axes to position 0 and clears G92 offsets.

```
STEPPER POSITION axis, position
```

Sets the current position of an axis (X/Y/Z in mm; A in degrees) to the specified value.

## 4. Advanced Features

```
STEPPER SCURVE 0|1
```

# PicoMite Stepper Motor Control Reference

Enables (1) or disables (0) S-curve acceleration profiling for smoother motion.

```
STEPPER JERK value
```

Sets the jerk limit in mm/s<sup>3</sup> for S-curve planning.

```
STEPPER SPINDLE pin [,invert]
```

Configures a spindle control pin used by buffered M3/M5 commands. Pin must not conflict with AXIS/HWLIMITS/E-STOP pins.

## 5. System Management

```
STEPPER RUN [,0|1]
```

Arms the system and begins executing buffered commands.

Optional mode argument controls behavior when the queue drains:

- 0 (default): remain armed with drivers enabled while idle.
- 1: when idle and no buffered work remains, drivers are disabled and then re-enabled automatically when new queued work arrives.

```
STEPPER CLEAR
```

Clears the G-code buffer (only when motion is idle).

```
STEPPER STATUS
```

Displays detailed system status, including axis positions, buffer state, and configuration (including auto-disable-on-idle mode).

```
STEPPER CLOSE
```

Shuts down the stepper subsystem, releases resources, and deconfigures stepper-owned GPIO pins.

```
PEEK( STEPPER X )  
PEEK( STEPPER Y )  
PEEK( STEPPER Z )  
PEEK( STEPPER A )  
PEEK( STEPPER ACTIVE )  
PEEK( STEPPER STATUS )  
PEEK( STEPPER BUFFER )
```

Returns current workspace axis position in mm (X/Y/Z) or degrees (A), or active state (ACTIVE returns 1 when stepper is actively processing queued work, 0 when idle, or -1 if the stepper subsystem has not been initialized).

STATUS returns a bitmap of safety and coordinate state:

- bit0: X\_MIN limit asserted
- bit1: X\_MAX limit asserted
- bit2: Y\_MIN limit asserted
- bit3: Y\_MAX limit asserted
- bit4: Z\_MIN limit asserted
- bit5: Z\_MAX limit asserted

# PicoMite Stepper Motor Control Reference

- bit6: E-STOP asserted
- bit7: position known (machine coordinates established).

BUFFER returns the number of free slots in the G-code circular buffer. This can be used to throttle G-code submission and avoid overflowing the buffer.

## 6. Rotary A Axis

The A axis is an optional fourth axis intended for rotary motion (degrees). It runs as a slave axis of the same Bresenham planner as X/Y/Z, but with rotary semantics:

- Units are degrees. `steps_per_unit` is steps/degree; max velocity input is deg/min (stored as deg/s); max acceleration is deg/s<sup>2</sup>.
- The A axis has no soft limits, no homing (G28 ignores A), and no hardware limit switch input. It is therefore not subject to STEPPER LIMITS or STEPPER HWLIMITS.
- For combined moves with XYZ, A travels alongside as a slave; the F word is mm/min over the XYZ Euclidean distance and A is clamped against its max velocity if it would otherwise exceed it.
- For A-only moves (no change in X, Y, or Z), the F word is treated as deg/min over |dA|.
- The A word is ignored on G2/G3 arc commands.
- G92 A<value> is supported and sets the A workspace offset.