

VGA check PicoMiteVGA

Vertical timing

Sync is negative polarity

Frame part	Lines	Time [ms]
Visible area	480	15.253227408143
Front porch	10	0.31777557100298
Sync pulse	2	0.063555114200596
Back porch	33	1.0486593843098
Whole frame	525	16.683217477656

Frame	Time [ms] measured	Error
Visible area		
Front Porch		
Sync Pulse	0.06353968254	
Back Porch		
Whole Frame	16.68333333	

Horizontal timing

Sync is negative polarity.

VGA 1 pixel (25MHz) is: 40ns

Measurement resolution is (PIO @126MHz/2) : 16ns

Scanline part	Pixels	Time [μ s]
Visible area	640	25.422045680238
Front porch	16	0.63555114200596
Sync pulse	96	3.8133068520357
Back porch	48	1.9066534260179
Whole line	800	31.777557100298

Scanline	Time [us] measured	Error (%)
Visible area	25.42857143 (+/- 0.016)	+0.02%
Front Porch	0.6507936508 (+/- 0.016)	+2.3% (15ns too long)
Sync Pulse	3.793650794 (+/- 0.016)	-0.51% (20ns too short)
Back Porch	1.904761905 (+/- 0.016)	-0.1%
Whole Line	31.77777778 (+/- 0.016)	0%

Assuming the VGA PIO in VGApicoMite is running 126MHz to achieve the 25MHz pixel clock, the vertical sync pulse looks 2 cycles to short, causing the backporch 2 cycles to long. This would however not cause the TheBackShed user “nbrok” complaining about blurring at right side of the VGA screen.

The above tolerances may cause “loosing” the leftmost pixel. But since the visible (horizontal) area is exact same size, there should be no shift in sampling during the visible area.

Above numbers are measured using a VGA picomite running V5.07.07 release. The HSYNC and VSYNC are generated by the picomite, and measured by the picomite. This will outrule crystal tolerances. So the numbers are clock cycle accurate.

Measuring HSYNC and VSYNC:

HSYNC and VSYNC are not connected to a monitor, but directly to GPO with a flying wire, and PIO 1 is used to measure the timing.

Measuring visible area and backporch/frontporch

No monitor is connected, the VGA RED pin is connected to either GPO or GP1 and generates a 3.3V logic signal when the screen RED. (there is no terminating 75 ohm resistor).

The HSYNC signal is connected to the other GPpin.

The program used for testing is:

You select a measurement mode by changing the label after RESTORE. This is very elementary, but does the job. The PWM is used to calibrate the measurement results.

```
'various measurements for digital signals using PIO

'generate test signal on GPO/1
'SetPin gp0,pwm  'CH 0a
'SetPin gp1,pwm  'CH 0b
'PWM 0, 1000, 60, 20
'

'pio setup, assign GPO as JMP pin
p=Pie(pinctrl 0,0,0,gp0,gp0,gp0,gp0)
e=Pie(execctrl gp0,0,31)
s=Pie(shiftctrl 0,0,0,0,0,0)
f=126e6
PIO init machine 1,0,f,p,e,s,0

'pio programs and start
Dim a%(7)
Restore fafa
Read inst,offs
For i=0 To 7: Read a%(i):Next
PIO program 1,a%()

PIO start 1,0

'mmbasic data handler from fifo's
'Check the the read data in MMBasic and print
Dim d%

Do
  k=0
  CLS RGB(red)
  For i=1 To 10
    PIO read 1,0,1,d%
    k=k+d%
  Next i
  d%=k/10
  Print "time =";1e6*(d%+offs)*inst/f;" us"
  Pause 1000
Loop
End

'----- PIO programs -----
'data format: inst,offs,program
' inst = number of instructions per loop
' offs = adjustment for instructions outside the loop

pul:
```

```

' measure pos pulse width on GP0
' line    code      mnemonics
' &h00    A02B      Mov X=-NULL
' &h01    2080      Wait until GP0=1
' &h02    0043      JMP (x<>0) x--, &h03
' &h03    00C2      JMP (GP0=1), &h02
' &h04    A0C9      MOV ISR = -X
' &h05    8000      Push noblock
' &h06    0000      JMP 0
Data 2,1,&hc200432080a02b,&h8000a0c9,0,0,0,0,0,0,0

pau:
'measure neg pulse width on GP0
' line    code      mnemonics
' &h00    A02B      Mov X=-NULL
' &h01    2000      Wait until GP0=0
' &h02    00C4      JMP (GP0=1), &h04
' &h03    0042      JMP (x<>0) x--, &h02
' &h04    A0C9      MOV ISR = -X
' &h05    8000      Push noblock
' &h06    0000      JMP 0
Data 2,-1,&h4200c42000a02b,&h8000a0c9,0,0,0,0,0,0,0

per:
'measure period on gp0
' line    code      mnemonics
' &h00    A02B      Mov X=-NULL
' &h01    0042      JMP (x<>0) x--, 2
' &h02    00C1      JMP (GP0=1), 1
' &h03    00C5      JMP (GP0=1) &h05
' &h04    0043      JMP (X<>0) X--, &h03
' &h05    A0C9      MOV ISR = -X
' &h06    8000      Push noblock
' &h07    0000      JMP 0
Data 2,3,&h0c500c10042a02b,&h8000a0c90043,0,0,0,0,0,0,0

fari:
'measure fall on gpl to rise on gp0
' line    code      mnemonics
' &h00    A02B      Mov X=-NULL
' &h01    2081      Wait until GP1=1
' &h02    2001      Wait until GP1=0
' &h03    00C5      JMP (GP0=1), &h05
' &h04    0043      JMP (x<>0) x--, &h03
' &h05    A0C9      MOV ISR = -X
' &h06    8000      Push noblock
' &h07    0000      JMP 0
Data 2,-1,&hc520012081a02b,&h8000a0c90043,0,0,0,0,0,0,0

riri:
'measure rise on gpl to rise on gp0
' line    code      mnemonics
' &h00    A02B      Mov X=-NULL
' &h01    2001      Wait until GP1=0
' &h02    2081      Wait until GP1=1
' &h03    00C5      JMP (GP0=1), &h05
' &h04    0043      JMP (x<>0) x--, &h03
' &h05    A0C9      MOV ISR = -X
' &h06    8000      Push noblock
' &h07    0000      JMP 0
Data 2,-1,&hc520812001a02b,&h8000a0c90043,0,0,0,0,0,0,0

fafafa:
'measure rise on gpl to rise on gp0
' line    code      mnemonics
' &h00    A02B      Mov X=-NULL
' &h01    2081      Wait until GP1=1
' &h02    2001      Wait until GP1=0
' &h03    0044      JMP (x<>0) x--, &h04
' &h04    00C3      JMP (GP0=1), &h03
' &h05    A0C9      MOV ISR = -X
' &h06    8000      Push noblock
' &h07    0000      JMP 0
Data 2,0,&h4420012081a02b,&h8000a0c900c3,0,0,0,0,0,0,0

```