


ANALOG INPUT
TO 45V DC
AMPS

CN2



+19V SUPPLY TO
DUINOMITE

Q6
BD139

R21
1K

R12
1K8

Q7
MPSA56

25
21V

U2
78L12

E5
100uF / 25V

GND